



The Work Book, Ground Floor, HiLITE Business Park
Kozhikode - 673014, Kerala, India.
E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com
Mob. & WhatsApp: +91 8138 00 29 84
MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Inspection

Date of Inspection:

15-01-2025

Customer Name:

Mrs. JIYA

Vehicle:

MARUTI SUZUKI BREZZA

Registration number:

P D I

Date of Registration:

15-01-2025

Model Year:

2024

Chassis Number:

MA3RYHL1SRK494794

Engine Number:

K15CN7558463

Kilometers at Inspection:

24

■ E- Exellent Condition

■ G- Good Condition

■ B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	●	○	○
Dash Pad	●	○	○
Glove Box	●	○	○
AC Cooling Performance & Heater Operations	●	○	○
Cigarette Lighter	○	○	○

INTERIOR CONDITION	E	G	B
Vanity Mirrors & Sun visors	☒	☐	☐
Hand brake lever / buttons	☒	☐	☐
Control buttons & levers	☒	☐	☐
Hood Release	☒	☐	☐

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	☐	☐	☐
Tachometer	☒	☐	☐
Temperature	☒	☐	☐
Oil Pressure	☒	☐	☐
Warning Messages & Symbols	☒	☐	☐
Audio System & Speakers	☒	☐	☐
Navigation System	☐	☐	☐
Keyless Entry / Ignition system	☒	☐	☐

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	☒	☐	☐
Front Carpeting	☒	☐	☐
Headliner & Head rests	☒	☐	☐
Rear Seats	☒	☐	☐
Rear Carpeting	☒	☐	☐
Trunk Carpeting	☒	☐	☐
Tools	☒	☐	☐
Jack	☒	☐	☐
Spare Tire	☒	☐	☐
Floor Pan	☒	☐	☐

ELECTRICAL SYSTEM	E	G	B
Head Lights	☒	☐	☐
Tail Lights	☒	☐	☐
Brake Lights	☒	☐	☐
Parking Lights	☒	☐	☐

ELECTRICAL SYSTEM	E	G	B
Turn Signals	☒	☐	☐
Electric Seats	☐	☐	☐
Sunroof Motors	☐	☐	☐
Power Window	☒	☐	☐
Blinds	☐	☐	☐
ORVM Electrical Mirrors	☒	☐	☐

UNDER THE HOOD	E	G	B
Fluids Condition	☒	☐	☐
Oil Leaks	☐	☐	☐
Coolant Leaks	☐	☐	☐
Drive Belts/Timing Belts	☒	☐	☐
Engine Mountings	☒	☐	☐
Steering Components	☒	☐	☐
Turbo	☐	☐	☐
All Rubber Boots/Gaiters	☒	☐	☐
Rat Bits	☐	☐	☐
Looped Wires	☐	☐	☐
Exhaust Leaks	☐	☐	☐
Exhaust Smoke	☒	☐	☐
Evidence of Smoke	☐	☐	☐
Abnormal Noise	☐	☐	☐

UNDER THE CAR	E	G	B
Drive Line	☒	☐	☐
Differential	☐	☐	☐
Under Body	☒	☐	☐
Exhaust	☒	☐	☐

ROAD TEST	E	G	B
Idle	☐	☐	☐
Engine Starting	☐	☐	☐

ROAD TEST	E	G	B
Acceleration	☐	☐	☐
Tyre Condition	☐	☐	☐
Engine Noise	☐	☐	☐
Steering Effort - Cornering Right or Left	☐	☐	☐
Engine Operating Temperature	☐	☐	☐
Transmission Shift Quality, Smoothness, Effort, Slippage	☐	☐	☐
Transmission/Transaxle Noise	☐	☐	☐
CV Joint/Drive Axle Noise	☐	☐	☐
Parking Brake Operation	☐	☐	☐
Engine Performance	☐	☐	☐
Cooling System Efficiency	☐	☐	☐

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	☒	☐	☐
Engine Condition	☒	☐	☐
Cooling Condition	☒	☐	☐
Interior Items	☒	☐	☐
Gauges	☒	☐	☐
Audio System	☒	☐	☐
Carpet & Upholstery	☒	☐	☐
Under the Hood	☒	☐	☐
Under the Car	☒	☐	☐
Electrical System	☒	☐	☐
Battery Condition	☒	☐	☐
Glass	☒	☐	☐
Trunk	☒	☐	☐
Tires & Wheels	☒	☐	☐
Car Scanning Report	☒	☐	☐
Road Test	☐	☐	☐

BREAK	
Noise	☐

BREAK	
Vibration	☐
Effort	☐

SUSPENSION	
OK	☒
Noise	☐
Rough	☐
Week	☐

COMMENTS

[View Images](#)

Name of Technician:Ebin

