

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

T	4.
Ing	pection
TILD	bection

Cigarette Lighter

Date of Inspection:	Customer Name:		
15-02-2025	*****		
Vehicle:	Registration number:		
AUDI A6	DL ****		
Date of Registration:	Model Year:		
25-11-2013	2014		
Chassis Number:	Engine Number:		
********1841	*****		
Kilometers at Inspection:  78251			
E- Exellent Condition	■ G- Good Condition	■ B- Bad	Conditio
INTERIOR CONDITION		E G	В
Door Panels		0	0
Dash Pad		0	0
Glove Box		0	0
AC Cooling Performance & Heate	er Operations	$\circ$	0

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0	•	0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0	•	0
Rear Seats	0	•	0
Rear Carpeting	0	•	0
Trunk Carpeting	0	•	0
Tools	0	0	0
Jack	0	0	0
Spare Tire	0	0	0
Floor Pan	0		0

ELECTRICAL SYSTEM	$\mathbf{E}$	G	В
Head Lights	0		0
Tail Lights	0	•	0
Brake Lights	0		0
Parking Lights	0		0

ELECTRICAL SYSTEM	$\mathbf{E}$	G	В
Turn Signals	0		0
Electric Seats	0	•	0
Sunroof Motors	0	•	0
Power Window	0	•	0
Blinds	0	0	0
ORVM Electrical Mirrors	0	0	0

UNDER THE HOOD	E	G	В
Fluids Condition	0	0	0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	0	•
Engine Mountings	0	0	•
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	0	•
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	0	0	0
Differential	0	0	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0	•	0
Engine Starting	0	•	0

ROAD TEST	E	G	В
Acceleration	0		0
Tyre Condition	0		0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0	•	0
Engine Performance	0	•	0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	${f E}$	G	В
Body Condition	0	0	0
Engine Condition	0	0	0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0		0
Carpet & Upholstery	0		0
Under the Hood	0	•	0
Under the Car	0		0
Electrical System	0		0
Battery Condition	0	•	0
Glass	0	•	0
Trunk	0	•	0
Tires & Wheels	0	•	0
Car Scanning Report	0	•	0
Road Test	0	•	0

BREAK	
Noise	

BREAK	
Vibration	
Effort	
SUSPENSION	
OK	

 $\sqrt{\phantom{a}}$ 

 $\checkmark$ 

## **COMMENTS**

Noise

Rough

Week

- \*\*NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.\*\*
- \* It appears that odometer tampering has occurred.
- \* There is an oil leak from the engine valve cover.
- \* The seal on the front right drive axle appears to be leaking.
- \* The front suspension parts have started to weaken (the upper arm bushes are cracked).
- \* The rear shock absorbers are starting to get weak, and the dust boots on the front shock absorbers are cracked.
- \* There is a power lag while driving the vehicle, a detailed check is required.
- \* The engine belt and rear brake pads have been replaced.
- \* There is an oil leak from the engine oil cooler.
- \* The inspection was stopped halfway as per the customer's request.

View Images

Name of Technician: Ebin



