



SURESH DRIVES AUTOCHECK LLP

The Work Book, Ground Floor, HiLITE Business Park
Kozhikode - 673014, Kerala, India.

E-mail: mail@sureshdrives.com | W: www.sureshdrives.com

Mob & Whatsapp: +91 8330 88 12 13

MSME: UDAYAM-KL-08-0089693 | GSTIN: 32AFPF54965Q1ZZ

Inspection

Date of Inspection:

15-09-2025

Customer Name:

Mr.*****

Vehicle:

MAHINDRA THAR ROXX

Registration number:

PDI

Date of Registration:

15-09-2025

Model Year:

2025

Chassis Number:

MA1UN4KY7S2H*****

Engine Number:

KYS4H*****

Kilometers at Inspection:

125

■ E- Exellent Condition

■ G- Good Condition

■ B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	☒	☐	☐
Dash Pad	☒	☐	☐
Glove Box	☒	☐	☐
AC Cooling Performance & Heater Operations	☒	☐	☐
Cigarette Lighter	☐	☐	☐
Vanity Mirrors & Sun visors	☒	☐	☐
Hand brake lever / buttons	☒	☐	☐

INTERIOR CONDITION	E	G	B
Control buttons & levers	☒	☐	☐
Hood Release	☒	☐	☐

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	☐	☐	☐
Tachometer	☐	☐	☐
Temperature	☒	☐	☐
Oil Pressure	☒	☐	☐
Warning Messages & Symbols	☒	☐	☐
Audio System & Speakers	☒	☐	☐
Navigation System	☐	☐	☐
Keyless Entry / Ignition system	☒	☐	☐

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	☒	☐	☐
Front Carpeting	☒	☐	☐
Headliner & Head rests	☒	☐	☐
Rear Seats	☒	☐	☐
Rear Carpeting	☒	☐	☐
Trunk Carpeting	☒	☐	☐
Tools	☒	☐	☐
Jack	☒	☐	☐
Spare Tire	☒	☐	☐
Floor Pan	☒	☐	☐

ELECTRICAL SYSTEM	E	G	B
Head Lights	☒	☐	☐
Tail Lights	☒	☐	☐
Brake Lights	☒	☐	☐
Parking Lights	☒	☐	☐
Turn Signals	☒	☐	☐
Electric Seats	☒	☐	☐

ELECTRICAL SYSTEM	E	G	B
Sunroof Motors	☒	☐	☐
Power Window	☒	☐	☐
Blinds	☐	☐	☐
ORVM Electric Mirrors	☒	☐	☐

UNDER THE HOOD	E	G	B
Fluids Condition	☒	☐	☐
Oil Leaks	☐	☐	☐
Coolant Leaks	☐	☐	☐
Drive Belts/Timing Belts	☒	☐	☐
Engine Mountings	☒	☐	☐
Steering Components	☒	☐	☐
Turbo	☒	☐	☐
All Rubber Boots/Gaiters	☒	☐	☐
Rat Bites	☐	☐	☐
Looped Wires	☐	☐	☐
Exhaust Leaks	☐	☐	☐
Exhaust Smoke	☒	☐	☐
Evidence of Smoke	☐	☐	☐
Abnormal Noise	☐	☐	☐

UNDER THE CAR	E	G	B
Drive Line	☒	☐	☐
Differential	☒	☐	☐
Under Body	☒	☐	☐
Exhaust	☒	☐	☐

ROAD TEST	E	G	B
Idle	☐	☐	☐
Engine Starting	☐	☐	☐
Acceleration	☐	☐	☐
Tyre Condition	☐	☐	☐

ROAD TEST	E	G	B
Engine Noise	☐	☐	☐
Steering Effort - Cornering Right or Left	☐	☐	☐
Engine Operating Temperature	☐	☐	☐
Transmission Shift Quality, Smoothness, Effort, Slippage	☐	☐	☐
Transmission/Transaxle Noise	☐	☐	☐
CV Joint/Drive Axle Noise	☐	☐	☐
Parking Brake Operation	☐	☐	☐
Engine Performance	☐	☐	☐
Cooling System Efficiency	☐	☐	☐

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	☒	☐	☐
Engine Condition	☒	☐	☐
Cooling Condition	☒	☐	☐
Interior Items	☒	☐	☐
Gauges	☒	☐	☐
Audio System	☒	☐	☐
Carpet & Upholstery	☒	☐	☐
Under the Hood	☒	☐	☐
Under the Car	☒	☐	☐
Electrical System	☒	☐	☐
Battery Condition	☒	☐	☐
Glass	☒	☐	☐
Trunk	☒	☐	☐
Tires & Wheels	☒	☐	☐
Car Scanning Report	☒	☐	☐
Road Test	☐	☐	☐

BRAKE	
Noise	☐
Vibration	☐
Effort	☐

SUSPENSION	
OK	☒
Noise	☐
Rough	☐
Weak	☐

COMMENTS

NOTE:This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.*

1.The vehicle's front left fender has been painted.

[View Images](#)

Name of Technician:Shibin Babu CTK

