

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Inspect	ion
---------	-----

Date of Inspection:	Customer Name:	
04-12-2024	Mr.ASWIN	
Vehicle:	Registration number:	
HARRIOR	KL 13 AS 3355	
Date of Registration:	Model Year:	
04-12-2024	2020	
Chassis Number:	Engine Number:	
MAT631523LPH55156	-	
Kilometers at Inspection: 53132		
E- Exellent Condition	■ G- Good Condition	■ B- Bad Conditio
- Exellent Condition	a- doud Condition	B- Bad Condition
INTERIOR CONDITION		E G B
Door Panels		0 • 0
Dash Pad		0 0
Glove Box		

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0	•	0
Rear Seats	0	•	0
Rear Carpeting	0	•	0
Trunk Carpeting	0		0
Tools	0		0
Jack	0	•	0
Spare Tire	0		0
Floor Pan	0	•	0

ELECTRICAL SYSTEM	\mathbf{E}	G	В
Head Lights	0		0
Tail Lights	0	•	0
Brake Lights	0		0
Parking Lights	0		0

ELECTRICAL SYSTEM	E	G	В
Turn Signals	0		0
Electric Seats	0	•	0
Sunroof Motors	0	•	0
Power Window	0	•	0
Blinds	0	0	0
ORVM Electrical Mirrors	0	•	0

UNDER THE HOOD	E	G	В
Fluids Condition	0		0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	0	0
All Rubber Boots/Gaiters	0	0	•
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	•	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	•	0
Abnormal Noise	0	•	0

UNDER THE CAR	E	G	В
Drive Line	0	•	0
Differential	0	0	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0	•	0
Engine Starting	0	•	0

ROAD TEST	E	G	В
Acceleration	0		0
Tyre Condition	0		0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0	•	0
Transmission Shift Quality, Smoothness, Effort, Slippage	0	•	0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0	•	0
Engine Performance	0		0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	${f E}$	G	В
Body Condition	0	•	0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0	•	0
Audio System	0	•	0
Carpet & Upholstery	0	•	0
Under the Hood	0	•	0
Under the Car	0	•	0
Electrical System	0	•	0
Battery Condition	0	•	0
Glass	0	•	0
Trunk	0		0
Tires & Wheels	0		0
Car Scanning Report	0	•	0
Road Test	0	•	0

BREAK	
Noise	

BREAK		
Vibration		
Effort		
SUSPENSION		
OK		
Noise		
Rough		
Week		
	'	

COMMENTS

NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.

*Front both side lower arm bush crack

*Turbo hose leak found

*Valve cover leak found

*Boot replaced and (rear left door replaced under Warranty)

View Images

Name of Technician: Gokul



