

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India. E-mail: sureshdrives@gmaiLcom | W: www.sureshdrives.com Mob. & WhatsApp: +91 8138 00 29 84 MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

## Inspection

Date of Inspection:	Customer Name:
19-12-2024	Mr.SHEJIN
Vehicle:	Registration number:
Mahindra XUV500	KL 76 ****
Date of Registration:	Model Year:
19-12-2024	2019
Chassis Number:	Engine Number:

MA1YU2WTUK6G11617	WTK4G12172
-------------------	------------

Kilometers at Inspection:

24136

E- Exellent Condition

📒 G- Good Condition

B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	0		0
Dash Pad	0		$\bigcirc$
Glove Box	0		0
AC Cooling Performance & Heater Operations	0		0
Cigarette Lighter	0	0	0

INTERIOR CONDITION	E	G	B
Vanity Mirrors & Sun visors	0	$\bigcirc$	0
Hand brake lever / buttons	0	$\bigcirc$	0
Control buttons & levers	0	$\bigcirc$	0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	0	$\bigcirc$	0
Tachometer	0	$\bigcirc$	0
Temperature	0	$\bigcirc$	0
Oil Pressure	0	$\bigcirc$	0
Warning Messages & Symbols	0	$\bigcirc$	0
Audio System & Speakers	0	$\bigcirc$	0
Navigation System	0	0	0
Keyless Entry / Ignition system	0	$\bigcirc$	0

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	0		0
Front Carpeting	0	$\bigcirc$	0
Headliner & Head rests	0	$\bigcirc$	0
Rear Seats	0	$\bigcirc$	0
Rear Carpeting	0	$\bigcirc$	0
Trunk Carpeting	0	$\bigcirc$	0
Tools	0	$\bigcirc$	0
Jack	0	$\bigcirc$	0
Spare Tire	0	$\bigcirc$	0
Floor Pan	0	$\bigcirc$	0

ELECTRICAL SYSTEM	E	G	B
Head Lights	0	0	0
Tail Lights	0		0
Brake Lights	0	۲	0
Parking Lights	0	۲	0

ELECTRICAL SYSTEM	E	G	В
Turn Signals	0	$\bigcirc$	0
Electric Seats	0	0	0
Sunroof Motors	0	0	0
Power Window	0	$\odot$	0
Blinds	0	0	0
ORVM Electrical Mirrors	0	$\bigcirc$	0

UNDER THE HOOD	E	G	B
Fluids Condition	$\bigcirc$	۲	$\bigcirc$
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	۲	0
Engine Mountings	0	۲	0
Steering Components	0	0	۲
Turbo	0	۲	0
All Rubber Boots/Gaiters	0	۲	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	۲	0
Exhaust Smoke	0	۲	0
Evidence of Smoke	0	۲	0
Abnormal Noise	0	0	۲

UNDER THE CAR	E	G	B
Drive Line	0	۲	0
Differential	0	0	0
Under Body	0	۲	0
Exhaust	0	۲	0

ROAD TEST	E	G	B
Idle	0	$\bigcirc$	0
Engine Starting	0	$\bigcirc$	0

ROAD TEST	E	G	B
Acceleration	0	$\bigcirc$	0
Tyre Condition	0	0	$\bigcirc$
Engine Noise	0	$\bigcirc$	0
Steering Effort - Cornering Right or Left	0	$\bigcirc$	0
Engine Operating Temperature	0	$\bigcirc$	0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0		0
Engine Performance	0	$\bigcirc$	0
Cooling System Efficiency	0	$\bigcirc$	0

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	0		0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		$\bigcirc$
Audio System	0		$\bigcirc$
Carpet & Upholstery	0		$\bigcirc$
Under the Hood	0		0
Under the Car	0		0
Electrical System	0		0
Battery Condition	0		0
Glass	0		$\bigcirc$
Trunk	0		$\bigcirc$
Tires & Wheels	0	0	
Car Scanning Report	0	۲	0
Road Test	0	۲	0

BREAK	
Noise	

BREAK	
Vibration	
Effort	

SUSPENSION	
ОК	
Noise	
Rough	
Week	

## COMMENTS

\*\*NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.\*\*

\*Right headlight replaced

\*Abnormal noise from steering column

\*3 tyre in 2019 manufactured and front right tyre 2024-Rear left tyre damage

View Images

Name of Technician:Gokul



