

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Inspection
------------

Date of Inspection:	Customer Name:			
06-01-2025	CERTIFICATE			
Vehicle:				
VOLKSWAGEN TAIGUN TOPLINE	Registration number:			
1.0 TSI MT	KL 23 U ****			
Date of Registration:	Model Year:			
16-05-2022	2022			
Chassis Number:	Engine Number:			
MEXA22CW4NT0****	DTB0****			
Kilometers at Inspection:  18022				
- Exellent Condition	Good Condition	■ E	3- <mark>B</mark> ad	Condition
NTERIOR CONDITION		E	G	В
Ooor Panels		0	•	0
Dash Pad		0	•	0
Glove Box		0	0	0
AC Cooling Performance & Heater Operations				

INTERIOR CONDITION	E	G	В
Cigarette Lighter	0	0	0
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	$\mathbf{E}$	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0		0
Rear Seats	0		0
Rear Carpeting	0		0
Trunk Carpeting	0		0
Tools	0	•	0
Jack	0		0
Spare Tire	0	•	0
Floor Pan	0		0

ELECTRICAL SYSTEM	E	G	В
Head Lights	0		0
Tail Lights	0		0
Brake Lights	0		0

ELECTRICAL SYSTEM	E	G	В
Parking Lights	0		0
Turn Signals	0	•	0
Electric Seats	0	•	0
Sunroof Motors	0	•	0
Power Window	0		0
Blinds	0		0
ORVM Electrical Mirrors	0		0

UNDER THE HOOD	E	G	В
Fluids Condition	0		0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	0	0
All Rubber Boots/Gaiters	0	•	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	0	•	0
Differential	0	0	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0	•	0

ROAD TEST	E	G	В
Engine Starting	0		0
Acceleration	0		0
Tyre Condition	0		0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0	<ul><li>•</li></ul>	0
Parking Brake Operation	0	<ul><li>•</li></ul>	0
Engine Performance	0		0
Cooling System Efficiency	0	<ul><li>•</li></ul>	0

FINAL INSPECTION SUMMARY	${f E}$	G	В
Body Condition	0		0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0		0
Carpet & Upholstery	0		0
Under the Hood	0		0
Under the Car	0		0
Electrical System	0		0
Battery Condition	0		0
Glass	0	0	
Trunk	0		0
Tires & Wheels	0	•	0
Car Scanning Report	0		0
Road Test	0		0

Noise	
Vibration	
Effort	

SUSPENSION	
OK	
Noise	
Rough	
Week	

## **COMMENTS**

- \*\*NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.\*\*
- \* There is a small crack in the front windshield.
- \* The two front headlights have been replaced.

View Images

Name of Technician:Ebin



