

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India. E-mail: sureshdrives@gmaiLcom | W: www.sureshdrives.com Mob. & WhatsApp: +91 8138 00 29 84 MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Inspection

Date of Inspection:	Customer Name:	
24-03-2025	Mr.XXXXX	

Vehicle:	Registration number:	
VOLVO XC 90 D5 inscription	KL 07 CM XXXX	

Date of Registration:	Model Year:
16-01-2018	2017

Chassis Number:

Engine Number:

YV1LF68ACJ13XXXXX	22XXXXX
-------------------	---------

Kilometers at Inspection:

102911

E- Exellent Condition

📒 G- Good Condition

B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	0	\bigcirc	\bigcirc
Dash Pad	0	\bigcirc	0
Glove Box	0	\bigcirc	0
AC Cooling Performance & Heater Operations	0	\bigcirc	0
Cigarette Lighter	0	0	0

INTERIOR CONDITION	E	G	B
Vanity Mirrors & Sun visors	0	\bigcirc	0
Hand brake lever / buttons	0	\bigcirc	0
Control buttons & levers	0	\bigcirc	0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	0		0
Tachometer	0		0
Temperature	0	\bigcirc	0
Oil Pressure	0	\bigcirc	0
Warning Messages & Symbols	0	\bigcirc	\bigcirc
Audio System & Speakers	0	\bigcirc	0
Navigation System	0	0	\bigcirc
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	0		0
Front Carpeting	0	\bigcirc	0
Headliner & Head rests	0	\bigcirc	0
Rear Seats	0	\bigcirc	0
Rear Carpeting	0	\bigcirc	0
Trunk Carpeting	0	\bigcirc	0
Tools	0	\bigcirc	0
Jack	0	\bigcirc	0
Spare Tire	0	\bigcirc	0
Floor Pan	0	\bigcirc	0

ELECTRICAL SYSTEM	E	G	B
Head Lights	0		0
Tail Lights	0		0
Brake Lights	0	۲	0
Parking Lights	0	۲	0

ELECTRICAL SYSTEM	E	G	B
Turn Signals	0	\bigcirc	0
Electric Seats	0	\odot	0
Sunroof Motors	0	۲	0
Power Window	0	۲	0
Blinds	0	0	0
ORVM Electrical Mirrors	0	۲	0

UNDER THE HOOD	E	G	B
Fluids Condition	0	0	0
Oil Leaks	0	0	\bigcirc
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	\bigcirc	0
Engine Mountings	0	0	۲
Steering Components	0		0
Turbo	0		0
All Rubber Boots/Gaiters	0		0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0		0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	Е	G	В
Drive Line	0	۲	0
Differential	0	۲	0
Under Body	0	۲	0
Exhaust	0	۲	0

ROAD TEST	E	G	B
Idle	0	0	0
Engine Starting	0	0	0

ROAD TEST	E	G	B
Acceleration	0	0	\bigcirc
Tyre Condition	0	0	0
Engine Noise	0	0	0
Steering Effort - Cornering Right or Left	0	0	0
Engine Operating Temperature	0	0	0
Transmission Shift Quality, Smoothness, Effort, Slippage	0	0	0
Transmission/Transaxle Noise	0	0	0
CV Joint/Drive Axle Noise	0	0	0
Parking Brake Operation	0	0	0
Engine Performance	0	0	0
Cooling System Efficiency	0	0	0

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	0	0	
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0		0
Carpet & Upholstery	0		0
Under the Hood	0		0
Under the Car	0		0
Electrical System	0		0
Battery Condition	0		0
Glass	0		0
Trunk	0	۲	0
Tires & Wheels	0	0	۲
Car Scanning Report	0	۲	0
Road Test	0	0	0

BREAK	
Noise	

BREAK	
Vibration	
Effort	

SUSPENSION	
ОК	
Noise	
Rough	
Week	

COMMENTS

NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.

- * The drive shafts on both front sides appear to be leaking.
- * It's time to replace both rear tires.
- * There is a large dent on the rear left fender.
- * There is an oil leak from the engine valve cover.
- * Haven't been able to test drive it because the owner isn't interested in doing a test drive.

View Images

Name of Technician:Ebin



