



The Work Book, Ground Floor, HiLITE Business Park
Kozhikode - 673014, Kerala, India.
E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com
Mob. & WhatsApp: +91 8138 00 29 84
MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Inspection

Date of Inspection:

30-06-2025

Customer Name:

Mr.XXXXX

Vehicle:

VOLKSWAGEN VIRTUS TOPLINE
1.0 TSI MT

Registration number:

KL-40-U-XXXX

Date of Registration:

04-04-2023

Model Year:

2022

Chassis Number:

MEXG22D27NT0XXXXX

Engine Number:

DTB0XXXXX

Kilometers at Inspection:

14625

■ E- Exellent Condition

■ G- Good Condition

■ B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	☐	☒	☐
Dash Pad	☐	☒	☐
Glove Box	☐	☒	☐
AC Cooling Performance & Heater Operations	☐	☒	☐

INTERIOR CONDITION	E	G	B
Cigarette Lighter	☐	☐	☐
Vanity Mirrors & Sun visors	☐	☒	☐
Hand brake lever / buttons	☐	☒	☐
Control buttons & levers	☐	☒	☐
Hood Release	☐	☒	☐

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	☐	☒	☐
Tachometer	☐	☒	☐
Temperature	☐	☒	☐
Oil Pressure	☐	☒	☐
Warning Messages & Symbols	☐	☒	☐
Audio System & Speakers	☐	☒	☐
Navigation System	☐	☐	☐
Keyless Entry / Ignition system	☐	☒	☐

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	☐	☒	☐
Front Carpeting	☐	☒	☐
Headliner & Head rests	☐	☒	☐
Rear Seats	☐	☒	☐
Rear Carpeting	☐	☒	☐
Trunk Carpeting	☐	☒	☐
Tools	☐	☒	☐
Jack	☐	☒	☐
Spare Tire	☐	☒	☐
Floor Pan	☐	☒	☐

ELECTRICAL SYSTEM	E	G	B
Head Lights	☐	☒	☐
Tail Lights	☐	☒	☐
Brake Lights	☐	☒	☐

ELECTRICAL SYSTEM	E	G	B
Parking Lights	☐	☒	☐
Turn Signals	☐	☒	☐
Electric Seats	☐	☐	☐
Sunroof Motors	☐	☒	☐
Power Window	☐	☒	☐
Blinds	☐	☐	☐
ORVM Electrical Mirrors	☐	☒	☐

UNDER THE HOOD	E	G	B
Fluids Condition	☐	☒	☐
Oil Leaks	☐	☐	☐
Coolant Leaks	☐	☐	☐
Drive Belts/Timing Belts	☐	☒	☐
Engine Mountings	☐	☒	☐
Steering Components	☐	☒	☐
Turbo	☐	☐	☐
All Rubber Boots/Gaiters	☐	☒	☐
Rat Bits	☐	☐	☐
Looped Wires	☐	☐	☐
Exhaust Leaks	☐	☐	☐
Exhaust Smoke	☐	☒	☐
Evidence of Smoke	☐	☐	☐
Abnormal Noise	☐	☐	☐

UNDER THE CAR	E	G	B
Drive Line	☐	☒	☐
Differential	☐	☐	☐
Under Body	☐	☒	☐
Exhaust	☐	☒	☐

ROAD TEST	E	G	B
Idle	☐	☒	☐

ROAD TEST	E	G	B
Engine Starting	☐	☒	☐
Acceleration	☐	☒	☐
Tyre Condition	☐	☒	☐
Engine Noise	☐	☒	☐
Steering Effort - Cornering Right or Left	☐	☒	☐
Engine Operating Temperature	☐	☒	☐
Transmission Shift Quality, Smoothness, Effort, Slippage	☐	☒	☐
Transmission/Transaxle Noise	☐	☒	☐
CV Joint/Drive Axle Noise	☐	☒	☐
Parking Brake Operation	☐	☒	☐
Engine Performance	☐	☒	☐
Cooling System Efficiency	☐	☒	☐

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	☐	☒	☐
Engine Condition	☐	☒	☐
Cooling Condition	☐	☒	☐
Interior Items	☐	☒	☐
Gauges	☐	☒	☐
Audio System	☐	☒	☐
Carpet & Upholstery	☐	☒	☐
Under the Hood	☐	☒	☐
Under the Car	☐	☒	☐
Electrical System	☐	☒	☐
Battery Condition	☐	☒	☐
Glass	☐	☒	☐
Trunk	☐	☒	☐
Tires & Wheels	☐	☒	☐
Car Scanning Report	☐	☒	☐
Road Test	☐	☒	☐

BREAK

Noise	☐
Vibration	☐
Effort	☐

SUSPENSION

OK	☒
Noise	☐
Rough	☐
Week	☐

COMMENTS

NOTE: *Please cross-check this inspection report with the vehicle's service history and insurance claim records before purchasing. This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.*

[View Images](#)

Name of Technician:Ebin

