



SURESH DRIVES AUTOCHECK LLP

The Work Book, Ground Floor, HiLITE Business Park
Kozhikode - 673014, Kerala, India.

E-mail: mail@sureshdrives.com | W: www.sureshdrives.com

Mob & Whatsapp: +91 8330 88 12 13

MSME: UDAYAM-KL-08-0089693 | GSTIN: 32AFDFS4965Q1ZZ

Inspection

Date of Inspection:

30-10-2025

Customer Name:

Mr.****

Vehicle:

Kia Carens

Registration number:

KL 18 AB ****

Date of Registration:

13-04-2022

Model Year:

2022

Chassis Number:

MZBGC813MNN01****

Engine Number:

-

Kilometers at Inspection:

63269

■ E- Excellent Condition

■ G- Good Condition

■ B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	☐	☒	☐
Dash Pad	☐	☒	☐
Glove Box	☐	☒	☐
AC Cooling Performance & Heater Operations	☐	☒	☐
Cigarette Lighter	☐	☐	☐
Vanity Mirrors & Sun visors	☐	☒	☐
Hand brake lever / buttons	☐	☒	☐

INTERIOR CONDITION	E	G	B
Control buttons & levers	☐	☒	☐
Hood Release	☐	☒	☐

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	☐	☒	☐
Tachometer	☐	☒	☐
Temperature	☐	☒	☐
Oil Pressure	☐	☒	☐
Warning Messages & Symbols	☐	☒	☐
Audio System & Speakers	☐	☒	☐
Navigation System	☐	☐	☐
Keyless Entry / Ignition system	☐	☒	☐

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	☐	☒	☐
Front Carpeting	☐	☒	☐
Headliner & Head rests	☐	☒	☐
Rear Seats	☐	☒	☐
Rear Carpeting	☐	☒	☐
Trunk Carpeting	☐	☒	☐
Tools	☐	☒	☐
Jack	☐	☒	☐
Spare Tire	☐	☒	☐
Floor Pan	☐	☒	☐

ELECTRICAL SYSTEM	E	G	B
Head Lights	☐	☒	☐
Tail Lights	☐	☒	☐
Brake Lights	☐	☒	☐
Parking Lights	☐	☒	☐
Turn Signals	☐	☒	☐
Electric Seats	☐	☐	☐

ELECTRICAL SYSTEM	E	G	B
Sunroof Motors	☐	☒	☐
Power Window	☐	☒	☐
Blinds	☐	☒	☐
ORVM Electric Mirrors	☐	☒	☐

UNDER THE HOOD	E	G	B
Fluids Condition	☐	☒	☐
Oil Leaks	☐	☐	☐
Coolant Leaks	☐	☐	☐
Drive Belts/Timing Belts	☐	☒	☐
Engine Mountings	☐	☐	☒
Steering Components	☐	☒	☐
Turbo	☐	☒	☐
All Rubber Boots/Gaiters	☐	☒	☐
Rat Bites	☐	☐	☐
Looped Wires	☐	☐	☐
Exhaust Leaks	☐	☐	☐
Exhaust Smoke	☐	☒	☐
Evidence of Smoke	☐	☐	☐
Abnormal Noise	☐	☐	☐

UNDER THE CAR	E	G	B
Drive Line	☐	☒	☐
Differential	☐	☐	☐
Under Body	☐	☒	☐
Exhaust	☐	☒	☐

ROAD TEST	E	G	B
Idle	☐	☒	☐
Engine Starting	☐	☒	☐
Acceleration	☐	☒	☐
Tyre Condition	☐	☒	☐

ROAD TEST	E	G	B
Engine Noise	☐	☒	☐
Steering Effort - Cornering Right or Left	☐	☒	☐
Engine Operating Temperature	☐	☒	☐
Transmission Shift Quality, Smoothness, Effort, Slippage	☐	☒	☐
Transmission/Transaxle Noise	☐	☒	☐
CV Joint/Drive Axle Noise	☐	☒	☐
Parking Brake Operation	☐	☒	☐
Engine Performance	☐	☒	☐
Cooling System Efficiency	☐	☒	☐

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	☐	☒	☐
Engine Condition	☐	☒	☐
Cooling Condition	☐	☒	☐
Interior Items	☐	☒	☐
Gauges	☐	☒	☐
Audio System	☐	☒	☐
Carpet & Upholstery	☐	☒	☐
Under the Hood	☐	☒	☐
Under the Car	☐	☒	☐
Electrical System	☐	☒	☐
Battery Condition	☐	☒	☐
Glass	☐	☒	☐
Trunk	☐	☒	☐
Tires & Wheels	☐	☒	☐
Car Scanning Report	☐	☒	☐
Road Test	☐	☒	☐

BRAKE	
Noise	☐
Vibration	☐
Effort	☐

SUSPENSION	
OK	☒
Noise	☐
Rough	☐
Weak	☐

COMMENTS

NOTE: *This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.

1. There are minor scratches on the vehicle's body.

2. Brake pads need to be changed.

[View Images](#)

Name of Technician: Shibin Babu CTK

