

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Ins	pection
	pecuon

Date of Inspection:	Customer Name:			
18-02-2025	Mr.XXXX			
Vehicle:	Registration number:			
MAHINDRA THAR ROXX	PDI			
Date of Registration:	Model Year:			
18-02-2025	2024			
Chassis Number:	Engine Number:			
MA1UN2JW7R2MXXXXX	JWR4MXXXXX			
Kilometers at Inspection: 37				
E- Exellent Condition	■ G- Good Condition		B- Bad	Condition
		-		
INTERIOR CONDITION Door Panels		E	G	В
Dash Pad		•	0	0
Glove Box		•	0	0
				0

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors		0	0
Hand brake lever / buttons		0	0
Control buttons & levers		0	0
Hood Release		0	0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer		0	0
Tachometer		0	0
Temperature		0	0
Oil Pressure		0	0
Warning Messages & Symbols		0	0
Audio System & Speakers		0	0
Navigation System	0	0	0
Keyless Entry / Ignition system	•	0	0

CARPET, UPHOLSTERY & TRUNK	${f E}$	G	В
Front Seats	•	0	0
Front Carpeting	•	0	0
Headliner & Head rests		0	0
Rear Seats		0	0
Rear Carpeting	•	0	0
Trunk Carpeting	•	0	0
Tools	•	0	0
Jack	•	0	0
Spare Tire	•	0	0
Floor Pan		0	0

ELECTRICAL SYSTEM	\mathbf{E}	G	В
Head Lights		0	0
Tail Lights		0	0
Brake Lights	•	0	0
Parking Lights	•	0	0

ELECTRICAL SYSTEM	E	G	В
Turn Signals		0	0
Electric Seats	•	0	0
Sunroof Motors	•	0	0
Power Window		0	0
Blinds	0	0	0
ORVM Electrical Mirrors	•	0	0

UNDER THE HOOD	E	G	В
Fluids Condition		0	0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts		0	0
Engine Mountings		0	0
Steering Components		0	0
Turbo		0	0
All Rubber Boots/Gaiters		0	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	•	0	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	•	0	0
Differential	•	0	0
Under Body	•	0	0
Exhaust	•	0	0

ROAD TEST	E	G	В
Idle	0	0	0
Engine Starting	0	0	0

ROAD TEST	E	G	В
Acceleration	0	0	0
Tyre Condition	0	0	0
Engine Noise	0	0	0
Steering Effort - Cornering Right or Left	0	0	0
Engine Operating Temperature	0	0	0
Transmission Shift Quality, Smoothness, Effort, Slippage	0	0	0
Transmission/Transaxle Noise	0	0	0
CV Joint/Drive Axle Noise	0	0	0
Parking Brake Operation	0	0	0
Engine Performance	0	0	0
Cooling System Efficiency	0	0	0

FINAL INSPECTION SUMMARY	E	G	В
Body Condition	•	0	0
Engine Condition	O	0	0
Cooling Condition	•	0	0
Interior Items	•	0	0
Gauges	•	0	0
Audio System	•	0	0
Carpet & Upholstery	•	0	0
Under the Hood	•	0	0
Under the Car	•	0	0
Electrical System	•	0	0
Battery Condition	•	0	0
Glass	•	0	0
Trunk	•	0	0
Tires & Wheels	•	0	0
Car Scanning Report	•	0	0
Road Test	0	0	0

BREAK	
Noise	

DREAK		
Vibration		
Effort		
SUSPENSION		
OK		
Noise		
Rough		

COMMENTS

Week

P D I inspection done.

View Images

Name of Technician:Ebin



