

SURESH DRIVES AUTOCHECK LLP

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: mail@sureshdrives.com | W: www.sureshdrives.com

Mob & Whatsapp: +91 8330 88 12 13

MSME: UDAYAM-KL-08-0089693 | GSTIN: 32AFPFS4965Q1ZZ

Ins	pection
1113	pecuon

Date of Inspection:	Customer Name:			
11-09-2025	Mr. XXXX			
Vehicle:	Registration number:			
KIA CARNIVAL	KL 05 AW XXXX			
Date of Registration:	Model Year:			
11-09-2025	2020			
Chassis Number:	Engine Number:			
MZBMC81AMLN0XXXXX	****			
E- Exellent Condition	■ G- Good Condition	E	3- Bad	Conditio
INTERIOR CONDITION		E	G	В
Door Panels Dash Pad		0	0	
Glove Box		0		0
AC Cooling Performance & Heater	Operations	0	0	0
Cigarette Lighter	Орогиноно	0	0	0
Vanity Mirrors & Sun visors		0	0	0
Vanity Mirrors & Siin visors		0		0

INTERIOR CONDITION	E	G	В
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0	•	0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0	0	
Front Carpeting	0		0
Headliner & Head rests	0		0
Rear Seats	0		0
Rear Carpeting	0		0
Trunk Carpeting	0		0
Tools	0		0
Jack	0		0
Spare Tire	0		0
Floor Pan	0	0	

ELECTRICAL SYSTEM	E	G	В
Head Lights	0	•	0
Tail Lights	0	•	0
Brake Lights	0	•	0
Parking Lights	0	•	0
Turn Signals	0	•	0
Electric Seats	0	•	0

ELECTRICAL SYSTEM	E	G	В
Sunroof Motors	0		0
Power Window	0		0
Blinds	0	0	0
ORVM Electric Mirrors	0		0

UNDER THE HOOD	E	G	В
Fluids Condition	0	0	•
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	•	0
Rat Bites	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	0	•	0
Differential	0	•	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	\mathbf{E}	G	В
Idle	0		0
Engine Starting	0	•	0
Acceleration	0	•	0
Tyre Condition	0	0	

ROAD TEST	E	G	В
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0		0
Engine Performance	0		0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	E	G	В
Body Condition	0	0	•
Engine Condition	0	•	0
Cooling Condition	0	•	0
Interior Items	0	•	0
Gauges	0	0	•
Audio System	0	•	0
Carpet & Upholstery	0	0	•
Under the Hood	0	•	0
Under the Car	0	•	0
Electrical System	0	•	0
Battery Condition	0	•	0
Glass	0	•	0
Trunk	0	•	0
Tires & Wheels	0	0	•
Car Scanning Report	0	•	0
Road Test	0	0	0

BRAKE	
Noise	
Vibration	
Effort	

SUSPENSION	
OK	
Noise	
Rough	
Weak	

COMMENTS

NOTE: *Please cross-check this inspection report with the vehicle's service history and insurance claim records before purchasing. This report reflects the vehicle's condition a the time of inspection and does not guarantee future performance.*

- * While checking the vehicle, it was found that an accident(major/total loss) had occurred on the rear right side and as a result, repair work had been carried out on this area.
- * It appears that the front driver's seat airbag and rear curtain airbag have been canceled, and the front left seat airbag has burst and been folded inward.
- * There is repaint with dent works in many parts of the body, the right side slide door has been replaced, and the wind shield glass has been replaced.
- * The glass in the cluster is missing, and the driver's door pasting was done a second time.
- * The right side slide door opening and closing is not working properly.
- * The floor panel near the right door is cracked.
- * Service is overdue, and it's time to replace the rear tires.
- * At the customer's request, the vehicle inspection was stopped and the remaining checks were waived.

View Images

Name of Technician: Ebin Raju



