

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

T		4
Ins	peci	tion

Date of Inspection:	Cust	omer Name:		
03-01-2025	C	ERTIFICATION		
Vehicle:	Regi	stration number:		
TOYOTA INNOVA CRYSTA	K	L 30 H ****		
Date of Registration:	Mod	el Year:		
26-08-2019	20	)19		
Chassis Number:	Engi	ne Number:		
MBJAB3EM0025****	20	GDA3****		
Kilometers at Inspection: 29209				
E- Exellent Condition	■ G- Good Co	ondition	<b>■</b> B-	Bad Condition
INTERIOR CONDITION			${f E}$	G B
Door Panels			0	• 0
Dash Pad			0	
Glove Box				

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0		0
Rear Seats	0	•	0
Rear Carpeting	0	•	0
Trunk Carpeting	0		0
Tools	0		0
Jack	0	•	0
Spare Tire	0		0
Floor Pan	0		0

ELECTRICAL SYSTEM	$\mathbf{E}$	G	В
Head Lights	0		0
Tail Lights	0	•	0
Brake Lights	0		0
Parking Lights	0		0

ELECTRICAL SYSTEM	E	G	В
Turn Signals	0	•	0
Electric Seats	0	•	0
Sunroof Motors	0	0	0
Power Window	0	•	0
Blinds	0	•	0
ORVM Electrical Mirrors	0	•	0

UNDER THE HOOD	E	G	В
Fluids Condition	0		0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	•	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	0	•	0
Differential	0	•	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0	•	0
Engine Starting	0	•	0

ROAD TEST	E	G	В
Acceleration	0		0
Tyre Condition	0	0	
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0	•	0
Transmission/Transaxle Noise	0	•	0
CV Joint/Drive Axle Noise	0	•	0
Parking Brake Operation	0	•	0
Engine Performance	0	•	0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	E	G	В
Body Condition	0		0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0		0
Carpet & Upholstery	0		0
Under the Hood	0		0
Under the Car	0	•	0
Electrical System	0	0	0
Battery Condition	0	0	0
Glass	0		0
Trunk	0	•	0
Tires & Wheels	0	0	•
Car Scanning Report	0	•	0
Road Test	0		0

BREAK	
Noise	

DRUAIX	
Vibration	
Effort	
SUSPENSION	
OK	
Noise	
Rough	
Week	

## **COMMENTS**

RREAK

- \*\*NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.\*\*
- \* All tyres meet service limit
- \* The front hood, right fender, right and left side headlights, bumper, grille, and radiator support have all been changed.

View Images

Name of Technician: Ebin



