

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

| T   |      | 4    |
|-----|------|------|
| Ins | peci | tion |

| Date of Inspection:              | Customer Name:       |             |         |
|----------------------------------|----------------------|-------------|---------|
| 18-01-2025                       | Mr. BIBIN            |             |         |
| Vehicle:                         | Registration number: |             |         |
| TATA HARRIER XZ+2.0L             | KL 08 BY ****        |             |         |
| Date of Registration:            | Model Year:          |             |         |
| 16-02-2022                       | 2022                 |             |         |
| Chassis Number:                  | Engine Number:       |             |         |
| MAT631555NPA****                 | 46343885-41****      |             |         |
| Kilometers at Inspection:  57335 |                      |             |         |
|                                  |                      |             |         |
| E- Exellent Condition            | ■ G- Good Condition  | ■ B- Bad Co | onditio |
| INTERIOR CONDITION               |                      | E G I       | В       |
| Door Panels                      |                      | 0           | 0       |
| Dash Pad                         |                      | 0           | 0       |
| Glove Box                        |                      |             | $\cap$  |

| INTERIOR CONDITION          | E | G | В |
|-----------------------------|---|---|---|
| Vanity Mirrors & Sun visors | 0 |   | 0 |
| Hand brake lever / buttons  | 0 |   | 0 |
| Control buttons & levers    | 0 |   | 0 |
| Hood Release                | 0 |   | 0 |

| GAUGES,AUDIO SYSTEM & NAVIGATION | E | G | В |
|----------------------------------|---|---|---|
| Speedometer                      | 0 |   | 0 |
| Tachometer                       | 0 |   | 0 |
| Temperature                      | 0 |   | 0 |
| Oil Pressure                     | 0 |   | 0 |
| Warning Messages & Symbols       | 0 |   | 0 |
| Audio System & Speakers          | 0 |   | 0 |
| Navigation System                | 0 | 0 | 0 |
| Keyless Entry / Ignition system  | 0 |   | 0 |

| CARPET, UPHOLSTERY & TRUNK | E | G | В |
|----------------------------|---|---|---|
| Front Seats                | 0 |   | 0 |
| Front Carpeting            | 0 |   | 0 |
| Headliner & Head rests     | 0 | • | 0 |
| Rear Seats                 | 0 | • | 0 |
| Rear Carpeting             | 0 | • | 0 |
| Trunk Carpeting            | 0 |   | 0 |
| Tools                      | 0 |   | 0 |
| Jack                       | 0 | • | 0 |
| Spare Tire                 | 0 |   | 0 |
| Floor Pan                  | 0 |   | 0 |

| ELECTRICAL SYSTEM | $\mathbf{E}$ | G | В |
|-------------------|--------------|---|---|
| Head Lights       | 0            |   | 0 |
| Tail Lights       | 0            | • | 0 |
| Brake Lights      | 0            |   | 0 |
| Parking Lights    | 0            |   | 0 |

| ELECTRICAL SYSTEM       | E | G | В |
|-------------------------|---|---|---|
| Turn Signals            | 0 |   | 0 |
| Electric Seats          | 0 | • | 0 |
| Sunroof Motors          | 0 | • | 0 |
| Power Window            | 0 | • | 0 |
| Blinds                  | 0 | 0 | 0 |
| ORVM Electrical Mirrors | 0 | • | 0 |

| UNDER THE HOOD           | E | G | В |
|--------------------------|---|---|---|
| Fluids Condition         | 0 | • | 0 |
| Oil Leaks                | 0 | 0 | 0 |
| Coolant Leaks            | 0 | 0 | 0 |
| Drive Belts/Timing Belts | 0 | • | 0 |
| Engine Mountings         | 0 | • | 0 |
| Steering Components      | 0 | • | 0 |
| Turbo                    | 0 | • | 0 |
| All Rubber Boots/Gaiters | 0 | • | 0 |
| Rat Bits                 | 0 | 0 | 0 |
| Looped Wires             | 0 | 0 | 0 |
| Exhaust Leaks            | 0 | 0 | 0 |
| Exhaust Smoke            | 0 | • | 0 |
| Evidence of Smoke        | 0 | 0 | 0 |
| Abnormal Noise           | 0 | 0 | 0 |

| UNDER THE CAR | <mark>ID</mark> |   | G | В |
|---------------|-----------------|---|---|---|
| Drive Line    | C               |   | • | 0 |
| Differential  | C               |   | • | 0 |
| Under Body    | C               | ) | 0 | 0 |
| Exhaust       | C               |   | • | 0 |

| ROAD TEST       | E | G | В |
|-----------------|---|---|---|
| Idle            | 0 | • | 0 |
| Engine Starting | 0 | • | 0 |

| ROAD TEST  | E | G | В |
|--|---|---|---|
| Acceleration   | 0 |   | 0 |
| Tyre Condition   | 0 |   | 0 |
| Engine Noise   | 0 |   | 0 |
| Steering Effort - Cornering Right or Left                | 0 |   | 0 |
| Engine Operating Temperature                             | 0 | • | 0 |
| Transmission Shift Quality, Smoothness, Effort, Slippage | 0 | • | 0 |
| Transmission/Transaxle Noise                             | 0 |   | 0 |
| CV Joint/Drive Axle Noise                                | 0 |   | 0 |
| Parking Brake Operation                                  | 0 | • | 0 |
| Engine Performance                                       | 0 |   | 0 |
| Cooling System Efficiency                                | 0 |   | 0 |

| FINAL INSPECTION SUMMARY | ${f E}$ | G | В |
|--------------------------|---------|---|---|
| Body Condition           | 0       | • | 0 |
| Engine Condition         | 0       |   | 0 |
| Cooling Condition        | 0       |   | 0 |
| Interior Items           | 0       |   | 0 |
| Gauges                   | 0       | • | 0 |
| Audio System             | 0       | • | 0 |
| Carpet & Upholstery      | 0       | • | 0 |
| Under the Hood           | 0       | • | 0 |
| Under the Car            | 0       | • | 0 |
| Electrical System        | 0       | • | 0 |
| Battery Condition        | 0       | • | 0 |
| Glass                    | 0       | • | 0 |
| Trunk                    | 0       |   | 0 |
| Tires & Wheels           | 0       |   | 0 |
| Car Scanning Report      | 0       | • | 0 |
| Road Test                | 0       | • | 0 |

| BREAK |  |
|-------|--|
| Noise |  |

| Vibration   |  |
|-------------|--|
| Effort      |  |
|             |  |
|             |  |
| SUSPENSION  |  |
| SUSPENSION  |  |
|             |  |
| OK<br>Noise |  |
| OK          |  |

## **COMMENTS**

\*\*NOTE: PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING.\*\*

 $\ensuremath{^{*}}$  The difference in readings is due to the PPF applied to the body.

View Images

Name of Technician: Ebin



