

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

IIISDECTION	Ins	pection
-------------	-----	---------

Date of Inspection:	Customer Name:	
08-04-2025	Mr.FADIL	
Vehicle:	Registration number:	
HYUNDAI CRETA	KL 13 AS ****	
Date of Registration:	Model Year:	
20-10-2020	2020	
Chassis Number:	Engine Number:	
MALPC811VLM07****	G4LDLG00 ****	
Kilometers at Inspection:  114636		
E- Exellent Condition	■ G- Good Condition	■ B- Bad Condition
INTERIOR CONDITION		E G B
Door Panels		0 • 0
Dash Pad		0 0
Glove Box		

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0	0	0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0		0
Rear Seats	0		0
Rear Carpeting	0		0
Trunk Carpeting	0		0
Tools	0		0
Jack	0		0
Spare Tire	0		0
Floor Pan	0		0

ELECTRICAL SYSTEM	E	G	В
Head Lights	0		0
Tail Lights	0	0	•
Brake Lights	0	•	0
Parking Lights	0	•	0

ELECTRICAL SYSTEM	${f E}$	G	В
Turn Signals	0	•	0
Electric Seats	0	•	0
Sunroof Motors	0	•	0
Power Window	0	•	0
Blinds	0	0	0
ORVM Electrical Mirrors	0	•	0

UNDER THE HOOD	E	G	В
Fluids Condition	0	•	0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	•	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0		0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	•	0
Abnormal Noise	0	•	0

UNDER THE CAR		E	G	В
Drive Line		0	•	0
Differential		0	0	0
Under Body		0	•	0
Exhaust	(	0		0

ROAD TEST	E	G	В
Idle	0	•	0
Engine Starting	0	•	0

ROAD TEST	E	G	В
Acceleration	0	•	0
Tyre Condition	0	0	0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0		0
Engine Performance	0		0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	E	G	В
Body Condition	0	•	0
Engine Condition	0	•	0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0	•	0
Carpet & Upholstery	0	•	0
Under the Hood	0	•	0
Under the Car	0	•	0
Electrical System	0	•	0
Battery Condition	0	•	0
Glass	0	•	0
Trunk	0	0	•
Tires & Wheels	0	0	0
Car Scanning Report	0	•	0
Road Test	0	•	0

BREAK	
Noise	

## **COMMENTS**

RREAK

\*\*\*NOTE:PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S SERVICE HISTORY BEFORE PURCHASING \*\*\*

\*Rear left tail light damage

\*Rear right tyre damage

View Images

Name of Technician:Gokul



