



SURESH DRIVES AUTOCHECK LLP

The Work Book, Ground Floor, HiLITE Business Park
Kozhikode - 673014, Kerala, India.

E-mail: mail@sureshdrives.com | W: www.sureshdrives.com

Mob & Whatsapp: +91 8330 88 12 13

MSME: UDAYAM-KL-08-0089693 | GSTIN: 32AFPF54965Q1ZZ

Inspection

Date of Inspection:

20-09-2025

Customer Name:

Mr XXXX

Vehicle:

Tata Safari XE 2.0 L Kyrotech BSVI

Registration number:

KL01CY XXXX

Date of Registration:

27-06-2023

Model Year:

2022

Chassis Number:

MAT631492NPCXXXXX

Engine Number:

46343885-41XXXXX

Kilometers at Inspection:

35654

■ E- Exellent Condition

■ G- Good Condition

■ B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	☐	☒	☐
Dash Pad	☐	☒	☐
Glove Box	☐	☒	☐
AC Cooling Performance & Heater Operations	☐	☒	☐
Cigarette Lighter	☐	☐	☐
Vanity Mirrors & Sun visors	☐	☒	☐
Hand brake lever / buttons	☐	☒	☐

INTERIOR CONDITION	E	G	B
Control buttons & levers	☐	☒	☐
Hood Release	☐	☒	☐

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	☐	☒	☐
Tachometer	☐	☒	☐
Temperature	☐	☒	☐
Oil Pressure	☐	☒	☐
Warning Messages & Symbols	☐	☒	☐
Audio System & Speakers	☐	☐	☐
Navigation System	☐	☐	☐
Keyless Entry / Ignition system	☐	☐	☐

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	☐	☒	☐
Front Carpeting	☐	☒	☐
Headliner & Head rests	☐	☒	☐
Rear Seats	☐	☒	☐
Rear Carpeting	☐	☒	☐
Trunk Carpeting	☐	☒	☐
Tools	☐	☒	☐
Jack	☐	☒	☐
Spare Tire	☐	☒	☐
Floor Pan	☐	☒	☐

ELECTRICAL SYSTEM	E	G	B
Head Lights	☐	☐	☐
Tail Lights	☐	☒	☐
Brake Lights	☐	☒	☐
Parking Lights	☐	☒	☐
Turn Signals	☐	☒	☐
Electric Seats	☐	☐	☐

ELECTRICAL SYSTEM	E	G	B
Sunroof Motors	☐	☐	☐
Power Window	☐	☒	☐
Blinds	☐	☐	☐
ORVM Electric Mirrors	☐	☐	☐

UNDER THE HOOD	E	G	B
Fluids Condition	☐	☒	☐
Oil Leaks	☐	☐	☐
Coolant Leaks	☐	☐	☐
Drive Belts/Timing Belts	☐	☒	☐
Engine Mountings	☐	☒	☐
Steering Components	☐	☒	☐
Turbo	☐	☒	☐
All Rubber Boots/Gaiters	☐	☒	☐
Rat Bites	☐	☐	☐
Looped Wires	☐	☐	☐
Exhaust Leaks	☐	☐	☐
Exhaust Smoke	☐	☒	☐
Evidence of Smoke	☐	☐	☐
Abnormal Noise	☐	☐	☐

UNDER THE CAR	E	G	B
Drive Line	☐	☒	☐
Differential	☐	☐	☐
Under Body	☐	☒	☐
Exhaust	☐	☒	☐

ROAD TEST	E	G	B
Idle	☐	☒	☐
Engine Starting	☐	☒	☐
Acceleration	☐	☒	☐
Tyre Condition	☐	☐	☐

ROAD TEST	E	G	B
Engine Noise	☐	☒	☐
Steering Effort - Cornering Right or Left	☐	☒	☐
Engine Operating Temperature	☐	☒	☐
Transmission Shift Quality, Smoothness, Effort, Slippage	☐	☒	☐
Transmission/Transaxle Noise	☐	☒	☐
CV Joint/Drive Axle Noise	☐	☒	☐
Parking Brake Operation	☐	☒	☐
Engine Performance	☐	☒	☐
Cooling System Efficiency	☐	☒	☐

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	☐	☒	☐
Engine Condition	☐	☒	☐
Cooling Condition	☐	☒	☐
Interior Items	☐	☒	☐
Gauges	☐	☒	☐
Audio System	☐	☐	☐
Carpet & Upholstery	☐	☒	☐
Under the Hood	☐	☒	☐
Under the Car	☐	☒	☐
Electrical System	☐	☒	☐
Battery Condition	☐	☒	☐
Glass	☐	☒	☐
Trunk	☐	☒	☐
Tires & Wheels	☐	☐	☐
Car Scanning Report	☐	☒	☐
Road Test	☐	☒	☐

BRAKE	
Noise	☐
Vibration	☐
Effort	☐

SUSPENSION

OK	☒
Noise	☐
Rough	☐
Weak	☐

COMMENTS

Extra Accessories Fitted

1) Android Sterio

2) Center Lock

3) Led Headlight Bulb

*Headlight Wiring Looped

*Front main Ac Grill Broken

* Lh side Rear View mirror indicator minor scratch

*Rear Right Tyre Damaged

*Rear Right Fender Minor Scratch

[View Images](#)

Name of Technician: Mohammed Sajith A

