

SURESH DRIVES AUTOCHECK LLP

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: mail@sureshdrives.com | W: www.sureshdrives.com

Mob & Whatsapp: +91 8330 88 12 13

MSME: UDAYAM-KL-08-0089693 | GSTIN: 32AFPFS4965Q1ZZ

T	4 •	
Ins	oecti	on

Date of Inspection:	Customer Name:			
13-11-2025	Mr.****			
Vehicle:	Registration number:			
MG Hector	KL 47 K ****			
Date of Registration:	Model Year:			
27-07-2021	2021			
Chassis Number:	Engine Number:			
MZ7BD1D2K3H03****	4075***			
E- Exellent Condition	G- Good Condition	■ B	⊱ Bad	Condition
INTERIOR CONDITION		E	G	В
Door Panels		0	•	0
Dash Pad		0		0
Glove Box		0		0
AC Cooling Performance & Heater Operation	ons	0		0
Cigarette Lighter		0	0	0
Vanity Mirrors & Sun visors				
		0	0	0

INTERIOR CONDITION	E	G	В
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0	•	0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0		0
Rear Seats	0		0
Rear Carpeting	0		0
Trunk Carpeting	0		0
Tools	0		0
Jack	0		0
Spare Tire	0		0
Floor Pan	0		0

ELECTRICAL SYSTEM	E	G	В
Head Lights	0		0
Tail Lights	0	•	0
Brake Lights	0	•	0
Parking Lights	0	•	0
Turn Signals	0	•	0
Electric Seats	0		0

ELECTRICAL SYSTEM	E	G	В
Sunroof Motors	0		0
Power Window	0		0
Blinds	0	0	0
ORVM Electric Mirrors	0		0

UNDER THE HOOD	\mathbf{E}	G	В
Fluids Condition	0		0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	•	0
Rat Bites	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	\mathbf{E}	G	В
Drive Line	0		0
Differential	0	0	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0		0
Engine Starting	0		0
Acceleration	0		0
Tyre Condition	0	0	

Engine Noise Steering Effort - Cornering Right or Left Engine Operating Temperature Transmission Shift Quality, Smoothness, Effort, Slippage Transmission/Transaxle Noise CV Joint/Drive Axle Noise			0
Engine Operating Temperature Transmission Shift Quality, Smoothness, Effort, Slippage Transmission/Transaxle Noise)	•	
Transmission Shift Quality, Smoothness, Effort, Slippage Transmission/Transaxle Noise)		
Transmission/Transaxle Noise			0
<u></u>)		0
CV Joint/Drive Axle Noise)		0
[C)		0
Parking Brake Operation			0
Engine Performance			0
Cooling System Efficiency			0

FINAL INSPECTION SUMMARY	E	G	В
Body Condition	0	O	0
Engine Condition	0	O	0
Cooling Condition	0	O	0
Interior Items	0	•	0
Gauges	0	•	0
Audio System	0	O	0
Carpet & Upholstery	0	O	0
Under the Hood	0	O	0
Under the Car	0	0	0
Electrical System	0	O	0
Battery Condition	0	O	0
Glass	0	O	0
Trunk	0	O	0
Tires & Wheels	0	O	0
Car Scanning Report	0	0	0
Road Test	0		0

BRAKE	
Noise	
Vibration	
Effort	

SUSPENSION	
OK	
Noise	
Rough	
Weak	

COMMENTS

NOTE: *This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.

View Images

Name of Technician: Shibin Babu CTK



